

(7)

**DELHI JAL BOARD: GOVT. OF NCT OF DELHI**  
**OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC)**  
**ROOM NO. 209, VARUNALAYA PHASE-I**  
**KAROL BAGH, NEW DELHI - 110005**  
**# 23558264**

No./DJB/EE(RWH/GWC)/2019/1879

DATED: 22/4/19

To,  
Principal,  
Himalaya Public Sr. Sec. School,  
D-12, Sec.07, Rohni, Delhi-85

**Subject:-Regarding adequacy of rain water harvesting system at Himalaya Public Sr. Sec. School, D-12, Sec.07, Rohni, Delhi-85.**

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on dated 16.04.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that two Nos. RWH pits are existing at site.

The existing RWH structures are adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structures are found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.

  
EE (RWH/GWC)

EE (G W CELL)  
DELHI JAL BOARD  
VARUNALAYA BHAWAN,  
JHANDEWALLAN, N.D.-05